

Employers are responsible for complying with the 2008 NEC 110.16 Labeling Requirements. We can fit your needs by assisting you in your own arc flash analysis or we can do a complete arc flash hazard analysis for you.


Assisting You in Your Arc Flash Analysis

Step 1: Using our software, you gather selected information about your electrical system.

Step 2: You send our engineers the information.

Step 3: Our engineers complete the Arc Flash Analysis and send you the warning labels, and the comprehensive Arc Flash Analysis Reports.

Complete Arc Flash Analysis Done for You



Our licensed electricians can collect and enter the data to create fault current and overcurrent protective device reports.

Provide arc flash calculations, create arc flash hazard labels for all points on one-line diagrams, and install labels on plant equipment.



Conduct meetings with personnel to explain findings and review recommendations.

Provide on site training with facility personnel and create a list of suggested PPE clothing needed.



For more information, contact us at
260-482-7099 or www.votawelectric.com